FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1.	Name of the Officer	J0920.
2	Name of the School	ALPAR-CENTRAL SCHOOL
3	Location with name of Education District/ Sub District	KATTOOR-18IN/IALAW ODA
4.	Classification of Building as specified in column 4 of the application for fitness certificate and size.	42:50X42:50X3.60 Three storied baild
5	Penod for which the certificate is issued	31-03-2022
6	Nature of defects , if any	
	a) Foundation and basement	
	b) Superstructure	•
	c) Doors and Windows	
	d) Wood work wrought and put up	1
	e) Roof	Nil
	f) Flooring	
	g) Miscellaneous (Cracks, etc.)	
7.	Any major defects noticed which will render the building unsafe in any manner	
8.	Whether maintenance works have been done properly	UPS
	Whether the structure is sound or not for conducting classes	Somdain for Normal West
N	ote: 1. The stability of the structure should be examined a exposure of flood etc. 2. Any additional observations if a separately with this certificate.	deemed necessary for the certification MANAGER MANAGER ALBA 3 CENTRAL SCHOOL
	CERTIFI	CATE (AII. 10 CBSE New Delhi No. 93067 P.O. KATTOOR, THRISSUR D KÉRALA - 680 702
	certified that the school building was inspected by me	e on 29-01-9099 and
found	d to be fit / unfit to conduct classes, for the period	21-03-2022
	ons stated above.	rthe
	28-01-2022 (5) (686)	MATTOOR MATTOO
SOUR-GLE	ALBAB CENTRAL SCHOOL Affiliated to CBSE. No.930673) Rattoor, Kerala, Pin-680 702	Assistant Engineer